



PRODUCTION INSTRUCTION OF PO - 1938 / AO-I T-54 / PLANE SIP-007-(25-26)

DESCRIPTION	17*25	25*70	24*36
Party Quality	1800	1800	1800
Party Weight	0.494	2.031	.972
Production Quality	2079	2079	2079
Production Weight	.560	2.300	1.120
Pile Height - A	0	0	0
Pile Height - B	0	0	0
Pile Height - C	0	0	0
Stitching 10 Cm A	0	0	0
Stitching 10 Cm B	0	0	0
Stitching 10 Cm C	0	0	0
Width in Line 5 cms	0	0	0
Niddle Gape / Weaving Com	CAM GAPE	CAM GAPE	CAM GAPE
1. Yarn UV/Non UV	UVC	UVC	UVC
2. Canvas UV/Non UV	CANVAS 53 .600 GSM	CANVAS 53 .600 GSM	CANVAS 53 .600 GSM
3. Canvas Size	53 INCH	53 INCH	53 INCH
4. Canvas Quality	.600 GSM	.600 GSM	.600 GSM
5. Canvas Weight @ PC.	0	0	0
6. Canvas Cutting Size	0	0	0
7. Pipen Tanki Fold	AS PER SAMPLE	AS PER SAMPLE	AS PER SAMPLE
8. Stiching in 5 CMS	8-9	8-9	8-9
9. Pipen Folder MM	AS PER SAMPLE	AS PER SAMPLE	AS PER SAMPLE
10. Latex	YES	YES	YES
11. Export Packing	NO	NO	NO

12. Carving	NO	NO	NO
TUMBLER / WASHING	NO	NO	NO
PC DYEING WEIGHT	.550	2.250	1.1
PC WASHING WEIGHT	0	0	0
TUMBLING WEIGHT	0	0	0
TUFFTING FINAL WEIGHT	.540-.560	2.200-2.300	1.080-1.120
EXTRA WORK WEIGHT	0	0	0
ORDER QUANTITY	200	100	700