



PRODUCTION INSTRUCTION OF PO - 1876 / AO-S E-14 / RT-17066 (REVERSIBLE)

DESCRIPTION	60*100	70*110	80*150	45*50	50*90	90*160	75*75	50*80	47*50
Party Quality	2200	2200	2200	2200	2200	2200	2200	2200	2200
Party Weight	1.321	1.692	2.638	.494	.990	3.167	.970	.880	.517
Production Quality	2421	2421	2421	2421	2421	2421	2421	2421	2421
Production Weight	1.453	1.863	2.900	.544	1.090	3.487	1.068	.885	.520
Pile Height - A	0	0	0	0	0	0	0	0	0
Pile Height - B	0	0	0	0	0	0	0	0	0
Pile Height - C	0	0	0	0	0	0	0	0	0
Stitching 10 Cm A	0	0	0	0	0	0	0	0	0
Stitching 10 Cm B	0	0	0	0	0	0	0	0	0
Stitching 10 Cm C	0	0	0	0	0	0	0	0	0
Width in Line 5 cms	0	0	0	0	0	0	0	0	0
Niddle Gape / Weaving Com	0	0	0	0	0	0	0	0	0
1. Yarn UV/Non UV	UVC	UVC	UVC	UVC	UVC	UVC	UVC	UVC	UVC
2. Canvas UV/Non UV	UVC	UVC	UVC	UVC	UVC	UVC	UVC	UVC	UVC
3. Canvas Size	70 INCH	70 INCH	70 INCH	70 INCH	70 INCH	70 INCH	70 INCH	70 INCH	70 INCH
4. Canvas Quality	.650 GSM	.650 GSM	.650 GSM	.650 GSM	.650 GSM	.650 GSM	.650 GSM	.650 GSM	.650 GSM
5. Canvas Weight @ PC.	0	0	0	0	0	0	0	0	0
6. Canvas Cutting Size	0	0	0	0	0	0	0	0	0
7. Pipen Tanki Form	AS PER SAMPLE	AS PER SAMPLE	AS PER SAMPLE	AS PER SAMPLE	AS PER SAMPLE	AS PER SAMPLE	AS PER SAMPLE	AS PER SAMPLE	AS PER SAMPLE
8. Stiching in 5 CMS	8-9	8-9	8-9	8-9	8-9	8-9	8-9	8-9	8-9
9. Pipen Folder Mark	AS PER SAMPLE	AS PER SAMPLE	AS PER SAMPLE	AS PER SAMPLE	AS PER SAMPLE	AS PER SAMPLE	AS PER SAMPLE	AS PER SAMPLE	AS PER SAMPLE
10. Latex	NO	NO	NO	NO	NO	NO	NO	NO	NO
11. Export Packing	NO	NO	NO	NO	NO	NO	NO	NO	NO

12. Carving	NO	NO	NO	NO	NO	NO	NO	NO	NO
TUMBLER / WASHING	NO	NO	NO	NO	NO	NO	NO	NO	NO
PC DYEING WEIGHT	1.421	1.821	2.837	.532	1.065	3.409	1.044	.867	.505
PC WASHING WEIGHT	0	0	0	0	0	0	0	0	0
TUMBLING WEIGHT	0	0	0	0	0	0	0	0	0
TUFFTING FINAL WEIGHT	1789-1.458	1789-2.863	1789-2.920	1789-1.544	1789-3.032	1789-3.402	1789-1.027	1789-1.058	1789-.885
EXTRA WORK WEIGHT	0	0	0	0	0	0	0	0	0
ORDER QUANTITY	105	65	60	115	90	35	25	35	30